

April 1, 2019 Reference No. 038443

Ms. Tamara McPeek
Environmental Response and Revitalization
Ohio Environmental Protection Agency
Southwest District Office
401 East Fifth Street
Dayton, Ohio
45402

Dear Ms. McPeek:

Re: MW-228 Well Decommissioning Summary South Dayton Dump and Landfill Site, Moraine, Ohio (Site)

This letter provides a summary and documentation of the well decommissioning for MW-228, in accordance with GHD's Well Location and Decommissioning Work Plan (Attachment 1 to GHD letter dated June 22, 2018 regarding Notice of Violation of OAC 3745-9-03[B] and OAC 3745-9-03[C]). GHD has prepared this letter on behalf of the Respondents to the Administrative Settlement Agreement and Order on Consent (ASAOC) for Remedial Investigation/Feasibility Study (RI/FS) of the Site, Docket No. V-W-16-C-011 (Respondents).

MW-228 was located on Valley Asphalt property at 1901 Dryden Road, Moraine, Ohio. Well construction details are provided in the stratigraphy log in Attachment 1, as well as in the Water Well Sealing Report #323035 in Attachment 2. The well was damaged as a result of the business operations at this property, i.e., stockpile of asphalt materials. Decommissioning of MW-228 was proposed to avoid possible future interference related to Valley Asphalt operations.

After removal of the reclaimed asphalt stockpile by Valley Asphalt, the well was located using field survey equipment, a metal detector, and an excavating machine. Decommissioning of MW-228 was completed by Cascade Drilling on February 21, 2019, and was overseen by a GHD field technician. The well was over drilled and the borehole grouted to the surface. Sealing procedures and materials used are detailed in the Water Well Sealing Report, provided in Attachment 2. In accordance with Ohio Revised Code 1521.05(C), on March 25, 2019, Cascade Drilling electronically filed the original well sealing report (Form #322955) with Ohio Department of Natural Resources (ODNR) Division of Geological Survey; Cascade Drilling electronically filed a corrected well sealing report (Form 323035) on March 21, 2019.





In addition, on September 6, 2018, MW-223B on Dayton Power and Light (DP&L) property was repaired by removing the overlying asphalt pavement and installing a new flush-mount cover in accordance with GHD's Well Location and Decommissioning Work Plan.

Should you have any questions on the above, please do not hesitate to contact us.

Sincerely,

GHD

Julian Hayward

Julian Hazuan

JH/kf/3

Encl.

cc: (all by pdf) Leslie Patterson, USEPA

Ken Brown, ITW Bryan Heath, NCR

Wendell Barner, Barner Consulting

Jim Campbell, EMI Andrew Dorn, ITW Brett Fishwild, Jacobs Valerie Chan, GHD

038443McPeek-3 2

Attachment 1



## STRATIGRAPHIC AND INSTRUMENTATION LOG (OVERBURDEN)

Page 1 of 2

PROJECT NAME: SOUTH DAYTON DUMP AND LANDFILL SITE

PROJECT NUMBER: 038443-70

CLIENT: PRP Group LOCATION: Moraine, Ohio HOLE DESIGNATION: MW-228

DATE COMPLETED: 26 March 2010

DRILLING METHOD: SONIC FIELD PERSONNEL: D. Rivers

EPTH t BGS	STRATIGRAPHIC DESCRIPTION & REMARKS  GROUND SURFACE		MONITOR INSTALLATION	SAMPLE				
1 000				NUMBER	INTERVAL	REC (%)	'N' VALUE	Headspace
				ĭ	Ξ	교	ž	ĘĘ
2	ASPHALT SP/GP - SAND & GRAVEL (FILL), trace silt; compact; fine to coarse sand; fine gravel; dark brown; moist	735.68						0.8
	CL - CLAY (FILL), with fine to coarse sand and fine gravel; firm; low plasticity; brown & gray; moist; trace brick debris	732.88						
1	RED BRICK DEBRIS (FILL)	731.88						
	MIX OF SAND & RED BRICK DEBRIS (FILL), compact; fine to coarse sand; poorly graded; dark gray to black sand; red & tan brick; moist	731.28						
6	MIX OF SAND, FLY ASH & BRICK DEBRIS (FILL), compact; fine to coarse sand; silt size fly ash; gray to black sand and fly ash; red and tan brick; moist	730.28	Bentonite Grout					
-	FLY ASH (FILL), compact; silt size; dark gray; wet; trace slag, glass and brick debris	727.88						1.7
10								
12	CL - CLAY (FILL), with silt; trace fine sand; firm; low plasticity; brown to dark gray; moist; trace fly ash	723.88						1.8
14								
16	SP/GP - SAND & GRAVEL (FILL), trace silt; fine to coarse sand; fine to coarse gravel; brown; moist; trace brick and concrete debris	721.38	2" PVC Casing Bentonite Chips					
	SM - SILTY SAND, trace fine to coarse gravel;	718.38						1.5



## STRATIGRAPHIC AND INSTRUMENTATION LOG (OVERBURDEN)

Page 2 of 2

PROJECT NAME: SOUTH DAYTON DUMP AND LANDFILL SITE

PROJECT NUMBER: 038443-70

CLIENT: PRP Group
LOCATION: Moraine, Ohio

HOLE DESIGNATION: MW-228

DATE COMPLETED: 26 March 2010

DRILLING METHOD: SONIC FIELD PERSONNEL: D. Rivers

EPTH	STRATIGRAPHIC DESCRIPTION & REMARKS		ELEV.	MONITOR INSTALLATION	SAMPLE				
t BGS			ft	me, m, e, c, m, e, c,	NUMBER	INTERVAL	REC (%)	'N' VALUE	Headspace PID (ppm)
20	compact; fine to coarse grained; poorly graded; light brown; moist								
22	SP - SAND, with fine to coarse gravel; trace silt; compact; fine to coarse grained; poorly graded; brown; moist		714.88						3.8
24	SW/GW - SAND & GRAVEL, trace silt; compact; fine to coarse sand; fine to coarse gravel; well graded; brown; moist to wet - wet at 23.5ft BGS		712.88	Sand Pack Well Screen					
26									
28									2.9
30	END OF BOREHOLE @ 30.0ft BGS		705.88	WELL DETAILS Screened interval: 716.88 to 706.88ft 19.00 to 29.00ft BGS Length: 10ft					
32				Diameter: 2in Slot Size: 10 Material: PVC Sand Pack: 718.88 to 705.88ft 17.00 to 30.00ft BGS Material: Sand size #5					
34				Sand Pack: 734.88 to 722.88ft 1.00 to 13.00ft BGS Material: Bentonite Grout					
NO.	ITES: MEASURING POINT ELEVATIONS MAY CHA	NIGE: DI	EED TO	CLIDDENT ELEVATION TABLE					

**Attachment 2** 

## WATER WELL SEALING REPORT e-FORM OHIO DEPARTMENT OF NATURAL RESOURCES Division of Soil and Water Resources

2045 Morse Road, Bldg B Columbus, OH 43229-6693 Voice: (614) 265-6740 Fax: (614) 265-6767

LOCATION								
County MONTGOMERY	Township MORAIN	Section No	Lot No					
Owner_VALLEY ASPHALT COI	RPORATION							
Address of Well Location 1901	DRYDEN RD							
City MORAINE	Zi <sub>'</sub>	p Code <u>45439</u>						
	JND ELEVATION AT MW-2	228: 735.88 FT. AMS	L					
Location of State Plane SWell in either:	x	+/ft. Y	ft.					
(Latitude/Longitu	ide Latitude 39.729159	Longitude <u>-8</u> 4	1.217502					
Elevation of Well	+/ ft. Datum Plane: [	NAD27 🗶 NAD83						
Source of Coordinates: GPS	Survey X Other GLOBAL	POSITIONING SYSTEM						
Source of Elevation: GPS	Survey Other							
		Project W	Project Well ID MW-228					
MEASURED CONSTRUCTION I	_							
Date of measurements								
	ft. \$		ft.					
Borehole Depth 30	ft. Borehole Diamete	er <u>6</u> in.	- 51.40					
Casing Diameter 2	<sub>in.</sub> Casing Length <u>1(</u>	<u>J</u> ft. Casing	Type PVC					
SEALING PROCEDURE	Sealing Material	Volume/Weight Us	sed Placement Method					
Placement:	20 . Dontonito alcum.	Units Required	Duran ad out house is a in a					
	30 ft. Bentonite slurry							
From ". To	ft							
	ft ft							
			10 Th					
Condition of Casing		Was Casing R	emoved? Yes or INO (check one)					
If casing <b>Not Removed</b> , was it P	erforated? Yes or No Pe	erforations: From	ft. To ft.					
Date Sealing Performed 2/21/2	,							
	AMAGED WELL. PRIOR TO SEALING W	VELL WAS OVER-DRILLED AND	CASING WAS REMOVED.					
CONTRACTOR								
Name CASCADE DRILLING LE	OD	)H Registration # 3506						
Address 1010 GREENE ST		=						
City/State/Zip MARIETTA, OH								
,								
e-Signature	CHRIS BUCHANAN tion given is accurate and correct to the best of my	Filed electronic	ally on <u>3/21/2019</u>					